

NEXT Truss

Harting breakout configuration

STANDARD AED BREAK OUT		
Pin	Phase	Wire
MOTOR 1		
1	L1	Brown
2	L2	Black
3	L3	Black/grey
MOTOR 2		
4	L1	Brown
5	L2	Black
6	L3	Black/grey
MOTOR 3		
7	L1	Brown
8	L2	Black
9	L3	Black/grey
MOTOR 4		
10	L1	Brown
11	L2	Black
12	L3	Black/grey
13	Not Connected	
14	Not Connected	
15	Not Connected	
16	Not Connected	
Chasis	GND	Ye/GR

STANDARD NL/SWISS/...		
Pin	Phase	Wire
MOTOR 1		
1	L1	Brown
2	L2	Black
3	L3	Black/grey
4	GND	Ye/GR
MOTOR 2		
5	L1	Brown
6	L2	Black
7	L3	Black/grey
8	GND	Ye/GR
MOTOR 3		
9	L1	Brown
10	L2	Black
11	L3	Black/grey
12	GND	Ye/GR
MOTOR 4		
13	L1	Brown
14	L2	Black
15	L3	Black/grey
16	GND	Ye/GR
Chasis	★	★

Hamburg standard + PRG + Chainmaster		
Pin	Phase	Wire
MOTOR 1		
1	L1	Brown
2	L2	Black
3	L3	Black/grey
MOTOR 2		
4	L1	Brown
5	L2	Black
6	L3	Black/grey
7	Not Connected	
8	Not Connected	
MOTOR 3		
9	L1	Brown
10	L2	Black
11	L3	Black/grey
MOTOR 4		
12	L1	Brown
13	L2	Black
14	L3	Black/grey
15	Not Connected	
16	Not Connected	
Chasis	GND	Ye/GR

Showtec Standard		
Pin	Phase	Wire
MOTOR 1		
1	L1	Brown
2	L2	Black
3	L3	Black/grey
4	Not Connected	
MOTOR 2		
5	L1	Brown
6	L2	Black
7	L3	Black/grey
8	Not Connected	
MOTOR 3		
9	L1	Brown
10	L2	Black
11	L3	Black/grey
12	Not Connected	
MOTOR 4		
13	L1	Brown
14	L2	Black
15	L3	Black/grey
16	Not Connected	
Chasis	GND	Ye/GR

